





6. Y-Gantry Assembly

Written By: Ryan Christy




Step 1 — X-Gantry



- Position the two Extrusion-F's on top of the Base-Assembly.
- Carefully slide the Y-Carriages on the X-Gantry through the Extrusion-F's
- Adjust the position of each Extrusion-F so the ends are flush with the corners of the Base-Assembly.


Step 2 — Y-End-Plates



- Prepare 2 x Y-End-Plate in the orientation shown in Image 1, with a M5-Button-Head-Bolt-12mm through each of the 4 bottom holes and a M5-Tee-Nut slightly threaded onto each one.
- The flat side of the M5-Tee-Nut should be facing the Y-End-Plate.
- Repeat the above 2 points, but for 2 x Y-End-Plate in the orientation shown Image 2.


This document was generated on 2021-12-25 06:08:58 PM (MST).

Step 3 — Attach Y-End-Plates




- At the front right corner of the machine, slide a Y-End-Plate into the two front-facing slots of Extrusion-A.
- Attach the Y-End-Plate to Extrusion-F using 4 x M5-Button-Head-Bolt-16mm through the non-threaded holes on the Y-End-Plate and into the threaded holes on Extrusion-F.
- Make sure the side of the Y-End-Plate is flush with the end of Extrusion-A.
 - Then tighten all the M5-Button-Head-Bolt-12mm on the Y-End-Plate.
- Repeat for the other 3 corners of the machine.

Step 4 — Binding Check




- Slide the X-Gantry to the back of the machine as far as it will go.
- Slightly loosen the 4 x M5-Button-Head-Bolt-12mm on each of the two front Y-End-Plates.
- **Carefully** slide the X-Gantry to the front of the machine as far as it will go.
- Re-tighten the M5-Button-Head-Bolt-12mm loosened in the green point above.
- Keep the machine at the front and slightly loosen the 4 x M5-Button-Head-Bolt-12mm on each of the two back Y-End-Plates.
- **Carefully** slide the X-Gantry to the back of the machine as far as it will go.
- Re-tighten the M5-Button-Head-Bolt-12mm loosened in the orange point above.
- ❗ Slide the X-Gantry back and forth. It should run smoothly without binding.

Step 5 — Lead Screws




- Insert a Lead-Screw-Y through the large 16mm hole on the front right Y-End-Plate so it protrudes into the channel on Extrusion-F roughly 100mm.
- Slide onto Lead-Screw-Y a Flanged-Radial-Bearing - ->- - Rubber-Bushing - ->- - Clamping-Collar.
- Insert the Lead-Screw-Y further into the channel, and then thread it through both Nut-Blocks on the Y-Carriage-Right.
 - ⓘ The Nut-Blocks should be loose so their position can be adjusted to allow Lead-Screw-X to thread through.
- Once through the Nut-Blocks, slide onto Lead-Screw-Y a Clamping-Collar - ->- - Rubber-Bushing - ->- - Flanged-Radial-Bearing.
- Thread through Lead-Screw-Y further so it goes through the large 16mm hole on the back right Y-End-Plate. Adjust the Lead-Screw so there is 14mm protruding from the back right Y-End-Plate.
- Seat the Flanged-Radial-Bearings into the Y-End-Plates, slide the Rubber-Bushing against the Flanged-Radial-Bearings and finally slide the Clamping-Collars so they are against against the Rubber-Bushings. Slightly tighten the Clamping-Collars.
- Repeat all the above points for the left Y-End-Plates and Y-Carriage-Left

Step 6 — Front Thrust Bearings




- ❗ Thrust-Bearings come in 3 parts. Thrust-Bearing-Housing-Washer, Thrust-Bearing-Caged-Roller and Thrust-Bearing-Shaft-Washer
- ❗ The Thrust-Bearing-Housing-Washer and Thrust-Bearing-Shaft-Washer look exactly the same. They are not.
- ⚠ Do not mix them up.
- On the Lead-Screw-Y protruding from the front right Y-End-Plate, slide on a Nylon-Shoulder-Washer ->- Thrust-Bearing-Housing-Washer ->- Thrust-Bearing-Caged-Roller ->- Thrust-Bearing-Shaft-Washer
- The Nylon-Shoulder-Washer seats in the 16mm hole on the Y-End-Plate.
- The Thrust-Bearing-Caged-Roller seats in the grooves on the Thrust-Bearing washers. Same orientation as before.
- Finally slide on a Clamping Collar. While pushing the Clamping-Collar against the Thrust-Bearing assembly, tighten the Clamping-Collar.
- Repeat all the above for the front left Y-End-Plate.

Step 7 — Back Thrust Bearings




- On the Lead-Screw-Y protruding from the back right Y-End-Plate slide on a Nylon-Shoulder-Washer - -> - Thrust-Bearing-Housing-Washer - -> - Thrust-Bearing-Caged-Roller - -> - Thrust-Bearing-Shaft-Washer
- The Nylon-Shoulder-Washer seats in the 16mm hole on the Y-End-Plate.
- The Thrust-Bearing-Caged-Roller seats in the grooves on the Thrust-Bearing washers. Same orientation as before.
- Finally slide on a Flexible-Coupler. While pushing the Flexible-Coupler against the Thrust-Bearing assembly, tighten Flexible-Coupler
- ① On the Flexible-Coupler tighten the clamping bolt first and then the grub screw.
- Repeat all the above for the back left Y-End-Plate.

Step 8 — Angle Corners



- At the front right corner of the machine, an Angle-Corner goes in the corner between Extrusion-A and Extrusion-F.
 - First slide an M5-Tee-Nut into the top slot of Extrusion-A.
 - ⓘ The flat face of the M5-Tee-Nut should be facing upwards.
 - Use a M5-Button-Head-Bolt-8mm and the previously inserted M5-Tee-Nut to attach it to Extrusion-A.
 - To attach it to Extrusion-F, use a M5-Button-Head-Bolt-8mm and M5-Drop-In-Tee-Nut.
 - M5-Drop-In-Tee-Nuts do not need to slide in from the end.
 - They go in to the slot parallel, when the bolt engages they should spin perpendicular to the slot and bite into the underside of the slot.


Step 9 — More Angle Corners



- Repeat the previous step for the other 3 corners.


⚠ Double-check the M5-Drop-In-Tee-Nuts are correctly engaged with Extrusion-F.

Step 10 — Left Y-Axis Stepper Motor





- Attach a Stepper-Motor to the threaded holes on the back left Y-End-Plate using 4 x M5-Cap-Head-Bolt-50mm and 4 x Aluminium-Spacer-40mms.
 - ① Orient the Stepper-Motor so that the wire is facing down.
 - ① The shaft of the Stepper-Motor goes into the Flexible-Coupler.
- ⚠ On the Stepper-Motor side make sure the Flexible-Coupler grub screw is on the flat portion of the Stepper-Motor shaft.**
- Once in position, tighten the clamping bolt first, then the grub screw.
 - ① The Lead-Screw side was tightened earlier in this guide.

Step 11 — Right Y-Axis Stepper Motor



- Repeat the previous step for the right Y-Axis Stepper-Motor.

Step 12 — End Caps



- Attach an End-Cap to the front left end of Extrusion-A using 2 x M5-Button-Head-Bolt-8mm.
- Repeat this for the other 3 bare ends of the Extrusion-A's.

Step 13 — Guide Complete



- i** Wow, what a difference. The machine can stay where it is now, we are going to be adding more stuff on!
- Guide Complete - Proceed to [7. Router Mount](#)

Thanks for following the guide. Any issues, please contact us!