





## 4. Wire Routing

Written By: Robert




## Step 1 — Cheat Sheet




- You are going to need our Motor Wire and Limit Switch [Cheat Sheet](#). We recommend printing it off!

## Step 2 — Z-Axis Wiring




- Motor-Wire-6 is coming out of the Moving End of Drag-Chain-X.
- Feed Motor-Wire-6 through the Drag-Chain-Mount and plug it into the pigtail on the Z-Axis Stepper-Motor.
- Feed the wire from Limit-Switch-2 through the Drag-Chain-Mount and then through Drag-Chain-X so it comes out the Fixed End.
- Secure the Limit-Switch-2 wire and Motor-Wire-6 together to the Drag-Chain-Mount using a small cable tie as in Image 2.
- Make sure there is enough slack on Motor-Wire-6 for the full travel of the Z-Axis.
- ① Any unneeded slack in both these wires should be pulled out at the Fixed End of the Drag-Chain-X.
- If you have the Touch Probe you can route that wire through Drag-Chain-X like [Step 4 of Assembling Your Original WorkBee XYZ Touch Probe](#)
- Secure the wire to the Drag-Chain-Mount using a small cable tie. Then secure it along Motor-Wire-6.

### Step 3 — Y-Axis Wiring



- Motor-Wire-5 is coming out of the Fixed End of Drag-Chain-Y.
  - Tuck this wire into the bottom slot of Extrusion-A
  - Plug it into the right Y-Axis Stepper-Motor (If looking from the front)
  - Motor-Wire-4 is coming out of the Fixed End of Drag-Chain-Y.
  - Plug it into the left Y-Axis Stepper-Motor (If looking from the front)
- ⓘ Any slack in both these wires should be pulled out at the Moving End of the Drag-Chain-Y.

### Step 4 — X-Axis Stepper Motor



- Plug Motor-Wire-3 into the X-Axis Stepper-Motor.
- Leave it hanging for now.

## Step 5 — Guide Complete



- ① That is all the wires routed. Now time to plug it all in!
- Guide Complete - Proceed to [5. Controller](#)

Thanks for following the guide. Any issues, please contact us!